
FABRICATED FITTINGS Transition PEHD DR11 x SS316 NPT IPS

А

L



PRODUCT 14032

	Size (in)		
1" Ø SDR 11	L	А	т
	8	4	1

PRODUCT 14033

	Size (in)		
1.25" Ø SDR 11	L	А	т
	8	4	1

PRODUCT 14034

	Size (in)		
2'' Ø SDR 11	L	А	т
	8	4	1



IMPORTANT - Do not use a pipe wrench ("PIPE WRENCH") to screw the transition, the tool can deform the steel cylinder and compromise the integrity and / or properties of the transition. It is recommended to use a CHAIN PIPE WRENCH to install the transition.

The information contained herein is provided without charge or obligation on the part of Sinoco inc. The person having this Information in their possession assumes all responsibility for its use, including ensuring that this technical sheet represents the latest update by contacting Sinoco inc. Sinoco inc. must be informed of any defect or non-conformity of the product before installation. The responsibility of Sinoco Inc. will be limited to the replacement of the nonconforming or defective product.

